


# Town of Hampden Capital Program Planning



Lura Hoit Pool	
P-1	Pool Sand Filter (replaced 2006)
P-2	Plaster Re-surface (replaced 2006)
P-3	Boilers (replaced 2009)
P-4	Pool Pump (replaced 2007)
P-5	Air Handler (replaced 2012)
P-6	Metal Roof (replaced 2014)
P-7	Painting inside of pool area
P-8	Sidewalk, curbing

Municipal	
M-1	Debt service payments on bonds issued
M-2	Municipal Building roof replacement (front)
M-3	Municipal Building (complete Public Safety flooring started in FY15)
M-3	LED lighting (municipal building)

Police & Fire	
PS-1	Fire Engine
PS-2	Air Bottles
PS-3	Ambulance
PS-4	Thermal Imaging Camera
PS-5	Handguns
PS-6	Cardiac Monitor (2)
PS-7	Pickup Truck

Library	
L-1	One flat roof surface needs to be replaced. Cost unknown.
L-2	Installation of LED lighting (King Grant supported)
L-3	Heating in the far ends of the building (Community Room & Children's Room) is not ideal. These rooms have large blowers which are loud and not very efficient.
L-4	All windows should be replaced as they are not efficient.

Public Works (non Sewer)	
Facilities	
PW-2	New salt shed
PW-3	Equipment garage
PW-4	Roof repair at DPW Garage
PW-5	New DPW office in location of existing garage (swap shop)
PW-6	Transfer Station reconfiguration

VFW	
R-3	Resurfacing/Repair of Tennis Courts
R-4	Resurfacing/Repair of Basketball Courts
R-5	Addition of permanent bathroom and concession space at Outdoor Field Space
R-6	Additional of outside storage space at Outdoor Field Space
R-7	Facility Signage

Skehan Center Items	
R-10	Additional parking, 60-70 additional spots needed
R-11	permanent secure lobby office space
R-12	Energy efficiency upgrades to building heating
R-13	Upgrades for locker room water heating

Notes:  
Map Prepared by: Kyle Severance  
Date of preparation: 5/18/2016  
Datum / Projection: NAD 83 Zone 19  
Data Sources: Town of Hampden, MEGIS, USGS, MDOT  
Parcel Layer last updated August 2015  
Disclaimer:  
This map was created to graphically represent the locations of items prepared under the Town of Hampden Capital Program Planning Budget Worksheets. The projects presented here are for discussion only and may or may not have been approved or funded.

Stormwater	
SW-1	Catch basins repair and maintenance. (423 within regulated urbanized area, including local and MDOT).
SW-2	Outfalls repair and maintenance. (93 within regulated urbanized area).
SW-3	Impaired watershed management plan, Shaw Brook
SW-4	Impaired watershed management plan, Sucker Brook

0 0.5 1 2 Miles

